Office of The District Fire Officer Karnataka Fire & Emergency Services Fire Station, Shivamogga-577201 Dated:29/07/2023

No.31(33)/FSR-CC/DFO/SD/2023

To

The Head Master/Principal , Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School, M L Halli, Sagara tq, Shivamogga Dist

Sir,

Sub: Issue of 'compliance report' with respect to fire prevention, fighting and evacuation measures maintained: required at "Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School" building constructed at Sy no:18, M L Halli, Sagara tq, Shivamogga Dist

Ref: 1) DFO Office SHIVAMOGGA Advice No.33/FSR/DFO/SMG/2023 Dated:- 24/07/2023.

Your letter dated 27/07/2023.

With reference to subject above cited, 'Fire Safety Recommendation' was issued wide reference (1) to the premises of "Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School" building with a condition to fulfill the recommendations and compliance the same within 3 months.

With reference cited (2) above, The Head Master/Principal , Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School, M L Halli, Sagara tq, Shivamogga Dist , had requested for the **compliance certificate** from our department. In this regard the Disrict Fire Officer, Shivamogga was inspected on 29/07/2023 to issue Compliance Certificate.

Under the above circumstances the Karnataka Fire & Emergency Services Department is issuing the 'Fire Safety Compliance Certificate' to "Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School" building situated at Sy no:18, M L Halli, Sagara tq, Shivamogga Dist, subject to proper maintenance of fire fighting installations in good working conditions and to arrange the training of 40% of employees within 3 months and to renewal the fire safety Recommendation report for every year.

Note: - This Certificate is not consider as a Fire Safety Recommendation Report.

Copy to:

1) The DDPI Officer, Shivmogga Taluk and District.

Yours faithfully,

District Fire Officer

Karnetaka Fire & Emergency Services

Fire Station, Shivamogga.

No 33/FSR/DFO/SMG/2023

TO.

Office of The District Fire Officer .

Karnataka Fire & Emergency Services
Fire Station, Shivamogga-577201

Date: 24 7 (202)

Head Master/Principal, Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School, M L Halli, Sagara tq, Shivamogga Dist

Sir

Sub: issue of fire safety recommendation to "Sri Ramakrishna Vasathi Vidyalaya and Sri Ramakrishna Vivekananda Residential School" building constructed at Sy no:18, M L Halli, Sagara tq Shivamogga Dist was inspected by the District fire officer Shivamogga on 21/07/2023 with respect to fire prevention, fire fighting and evacuation measures to be complied in the above premises and the details as under

A. Details of the building / premises :-

01. Name and Address of the : Head Master/Principal,

Applicant. Sri Ramakrishna Vasathi Vidyalaya and Sri

Ramakrishna Vivekananda Residential School, Sy no:18

M L Halli, Sagara tq, Shivamogga Dist

02. Name and Address of the : Sri Ramakrishna Vasathi Vidyalaya and Sri

premises. Ramakrishna Vivekananda Residential School, Sy no:18

M L Halli, Sagara tq, Shivamogga Dist

03. Name & address of the building : Managing Trustee,

owner Sri Ramakrishna Gurukulashrama Trust,

M L Halli, Sagara tq, Shivamogga Dist

04. Number of buildings : One

05. Number of floors : Ground +Three upper floors only

06. Floor-wise details of occupancy:-

Ground floor : Office room(1), Class rooms(15)

1st floor : Class rooms(18), Laboratary room (02)

2nd floor : Class rooms (15) 3rd floor : Class rooms (14)

07. Height of the building : 14.60 mtrs

08 Site area : 3.00 Acre

09. Built-up area of each floor:-

Ground floor : 1058.27 Sq mtr 1st floor : 1058.27 Sq mtr

1st floor : 1058.27 Sq mtr 2nd floor : 1058.27 Sq mtr 3rd floor : 1058.27 Sq mtr

10. Total built-up area : 4233.08 Sq mtr

Surrounding properties:-

East (Front) : 06.00 mtr wide road

West (Reary Dist. Hastel

North (Side) : Agriculture land

South (Side) : Agriculture land

12. Open space all around the building:

amonda.

7.00 Mtrs. East (Front) :

Nil West (Rear)

15.00 Mtrs North (Side)

Nil South (Side r) :

extinguishers

Allowed setbacks (open space) should be maintained free from further obstruction / construction

B. On inspection of this School/College premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-

Sl. No. (1)	Details (02)	Existing (03)			Recommendations (04)
01.	Accessibility to the Premises		oad	d, located on Eastern ardened to carry the	Adequate
02.	Number of entrances	One			Adequate
03.	Number of staircase	No. of staircases	:	02	Adequate
		Width of staircases Width of treads Height of risers	:	Each 01.00 mtrs Each 0.30 cm Each 0.15 cm	
		No. of risers per flight Height of handrails	:	Each 07Nos	
04.	Portable	Not provided			Not complied



- A. One water mist extinguisher of 9 ltrs capacity should kept near each staircase landing.
- B. One mechanical foam extinguisher of ltrs capacity & One ABC type extinguisher of capacity should be provided near diesel generator.
- CO₂ fire C. One type extinguisher, of 4.5 kgs capacity should be provided near each electrical panel board & electrical room.
- fire type ABC D. One extinguisher of 06 kgs



capacity should be located as to be available within 15 mtrs. radius.

 Hose reel hose system Not provided

Not complied

One Hose Reel Hose near the staircase (One hose reel hose system for every 1000 Sq. mtrs). The hose reel hose of min 19 mm size and of 30.00 mtrs length shall be provided to reach the farthest point of each floor and shut off branch having a nozzle of 5mm size. The hose reel hose should be connected at each landing.

 At the terrace tank level with minimum pressure of 3.5 kg/cm². Not provided

07 Diesel generator

Not provided

08. Terrace tank

Not provided

Not complied

The system should be connected to an booster pump of 450 LPM or of 5 HP capacity

Further the system should be connected to an alternative source of power supply.

Diesel generator of mim 15 KVA capacity should be provided to supply alternative power supply.

Not complied

The system should be connected to an over head tank of 5,000 ltrs capacity and further if basement is provided the tank capacity shall be increased to 10,000 ltrs capacity

(The water tank should be kept exclusively fire fight purpose)

Note: If the existing building is not capable of sustaining the weight of 5,000 / 10,000 ltrs tank capacity provision shall be made to provide water tank on the side of the building with support from ground level by providing RCC column structure or MS Column structure.

If there is no option to provide even the above mentioned



09 Escape routes	Not marked
10. Fire order	Not displayed
(Fire safety plans)	
11. No smoking board	Not displayed
12 Fire Siren	Not installed
13 Nominate one Fire Nodal Officer	••
14. Fire fighting training	Not imparted
	the Di

overhead tank provision shall be made to provide underground water tank of capacity with submersible pump of 5-7 HP capacity.

Not complied

Direction in which the students have to move in the event of an emergency should be displayed in the corridor on each floor during evacuation.

Not complied

A notice board have been indicated the action should be taken by the employees in case of any emergency should be displayed with the telephone number of Sagara Fire station i.e. 101, 112, 08183-226800 and the telephone number of nearest ambulance service & Police station.

Not complied

COTPA Sec-4 direction No Smoking area smoking here is an offence board should be written in English & Kannada both language shall be prominently displayed at inside the entry / exit of the each floor.

Not complied

A Fire Siren shall be installed in the premises to inform the inmates in case of a fire emergency and evacuate the area.

Not complied

A fire nodal officer shall be nominated either from teaching or non teaching staff.

At-least 40% of Teaching and non Teaching staff should be got trained in basic fire fighting at R.A. Mundkur Fire and Emergency Services Academy, Bannerughatta road, Bangalore or Regional Training centre

Fire precautionary measures:-

- A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- B. Accumulation of combustible waste in and around the premises should be avoided.
- C. The exit ways shall be always kept clear without any obstruction.
- D. Liquefied petroleum gas should not be stored in the building.
- E. The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F. During the class hours the class room doors shall not be locked from inside to outside.
- G. As per Hon'ble supreme court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordinate with fire service department.

Under the above circumstance the Karnataka Fire & Emergency Service Department is issuing '
Fire Safety Recommendation' to "Sri Ramakrishna Vivekananda Residential School" building constructed at M L Halli, Sagara tq Shivamogga Dist subject to condition and compliance of the above recommendations in column -4 of serial – B within 3 months and compliance to the undersigned. The Applicant has Remitted Rs, 5,000=00 (Rupees Five Thousand Only)Vide challan No.J-108013236 Dated 24/07/2023 At SBI PR Road Davanagere Branch Being Advice Fees.

This <u>Fire Safety Recommendation</u> is valid for only one year from the date of issue and it is renewable.

All Requirments Recommended Above Are As per National Building Code (NBC)-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2

ne Districe

Copy to:

01) The DDPI Officer Shivmogga district varnogga

Yours faithfully

2917170

District Fire Officer

Karnataka Fire & Emergency Services Fire Station, Shivamogga.